
















ASSEMBLY INSTRUCTION











PARTS

①  x1	②  x1	③  x1	④  x1
⑤  x1	⑥  x1	⑦  x1	⑧  x1
⑨  x1	⑩  x2	⑪  x1	⑫  x1
⑬  x1	⑭  x1	⑮  x1	⑯  x1

HARDWARE


Ⓐ  x16 +2(spare)	Ⓑ  x22 +2(spare)	Ⓒ  x22 +2(spare)	Ⓓ  x 4 4x30mm	Ⓔ  x1
Ⓕ  x 1 4x16mm	Ⓖ  x 4	Ⓗ  x13 +1(spare) 3x12mm	Ⓘ  x2 15mm	Ⓙ  x1
Ⓚ  x 2 3x14mm	Ⓛ  x 4 3x16mm	Ⓜ  x4	Ⓝ  x 1	Ⓞ  x 1
Ⓟ  x 1 3.5x40mm	Ⓠ  x1			

STEP 1




STEP 2


	Ⓑ x 4
	Ⓗ x 4
	Ⓘ x 2




STEP 3




STEP 4




STEP 5





STEP 6



STEP 7




STEP 8




STEP 9

	Ⓐ x 4
	Ⓒ x 2





STEP 10


	Ⓐ x 4
	Ⓒ x 2




STEP 11




STEP 12



STEP 13




STEP 14





STEP 15

	Ⓑ x 4
	ⓐ x 1
	Ⓚ x 2




STEP 16

	Ⓐ x 4
	Ⓒ x 4






STEP 17




STEP 18

	(H) x 3
	(M) x 4
	(L) x 4
	(O) x 1




STEP 19




STEP 20

	E x 1
	F x 1
	H x 2
	N x 1



STEP 21

	(H) x 4
---	---------



STEP 22

	(P) x 1
	(Q) x 1

